## General Environmental Incident Summary

*Incident:* 1983 *Notice:* 7/15/2013 1340 *Occurred:* 7/14/2013 1340

DEM Incident No: No Further Action:

Responsible Party: ND Army National Guard

County: Burleigh

**Twp Rng Sec Qtr:** 139 79 26 NW

Lat Long + Method: 46.83044 -100.61480 Derived from TRS

Location Description: Fairview Cemetary, Bismarck

Submitted By Info: NCO Brady Liesen

Received By Info: David Cameron

**NDDoH** 

Contact Info: Cmdr Badger Koepplin

46 W Museum Dr

Dickinson ND

Affected Medium: 03 - soil
Near. Occupied Bldg: 1000 Feet

Type of Incident: Vehicle Accident

Release Contained:

Reported to NRC: Unknown
Contaminant: diesel fuel
Volume of Release: 5 gallons
Duration of Release: 20 minutes

Agriculture Related: No

**EPA Extremely** 

Hazardous Substance: No Number of Fatalities: 0 Number of Injuries: 0

Cause of Incident:

scraper rollover at Fairview Cemetary project

Risk Evaluation:

low

Potential Env. Impacts:

minor soil

Action Taken/Planned:

1 1/4 yd of soil was recovered.

Wastes Disposal Location:

landfill

Other Agencies Involved:

## **Updates**

Date: 7/15/2013 Status: Reviewed - Follow-up Required

Author: Roberts, Kris

Notes:

Spill was not contained. Follow-up required.

Updated Volume: None at the time of this update

Date: 7/19/2013 Status: Inspection

Author: Stockdill, Scott

Notes:

Arrived on location at 11:00 AM 7/22/2013.

Toured site with Lieutenant in charge. Majority of spill cleaned up with little diesel remaining. Spill cleaned up appropriately. No photos taken.

No follow-up required.

Updated Volume: None at the time of this update